

DN65 SHJ, NISSAN LEAF

Registration: DN65 SHJ

Colour: RED

Appraised: 17/09/2021

Transmission: Automatic


Odometer: 36,352 miles

Equipment

Alloy Wheels

Climate Control

Exterior condition



- 1 Bumper Front; Dented; With Paint Damage

- 2 Bumper Rear; Scratched; Over 100mm Thru Paint

- 3 Door osf; Scratched; Over 25mm Thru Paint

- 4 Qtr Panel nsr; Scratched; Over 25mm Thru Paint

- 5 Bonnet; Dented; Between 10mm + 30mm

- 6 Door nsf; Scratched; UpTo 25mm Thru Paint

- 7 Wheel nsf; Scratched; Over 50mm



- 8 Wheel nsr; Scratched; Over 50mm

- 9 Wheel osf; Scratched; Over 50mm

- 10 Wing osf; Scratched; UpTo 25mm Thru Paint

- 11 Wing osf; Chipped; 1 To 5

Click to enlarge image





Interior condition

